




# ELK-SWP4 - Peripheral Mounting Guide




Universal Black Box  
Secure to plate using (2) #6-32  
type F thread cutting screws.



Universal Project Box  
Secure to plate using (2) #6-32  
type F thread cutting screws.




M1XEP




P1215 Charger Board




M1XIN, M1XOVR, M1RB, P212S




M1XSP




P624




ELK-965 & P624 COMBINATION



M1DBHR



ELK-100




ELK-101




ELK-110



ELK-120



ELK-930



ELK-960